

Wunder-Bar™

Automatic Bar Controls Inc.

TECHNICAL SERVICE BULLETIN

Date: 11/7/18



Product: Bar-Gun Manifold

Subject: Cracking Manifold (**Potential Failure Due to Poor Manifold Frame Structural Integrity**)

Symptoms of potential fault:

Special attention should be placed on the shut-off screw and surrounding frame region. If either of these are damaged or bent, the frame may crack and open a pressurized water or syrup line. Any sign of bending at the shut-off spade (finger hold on top of the shut-off) may be an indicator that the shut-off has been twisted beyond its normal limits and may have translated a crack to the frame.

Catastrophic blow out, typically located in the center of the manifold where higher pressures develop.



Serial Number Identification

Curative Action:

Review for Cracks and/or breaks & replace per instructions. Document manifold and contact Wunder-Bar for replacement.

Serial Numbers between – 000901759 - 000958207

Additional Information: Written instructions & videos can be located at

<https://www.wunderbar.com/support/service-bulletin>

If you need further details please contact Wunderbar service at 1-866-986-3372 or Service@wunderbar.com